









114



214



3/4




FIG 4a




FIG 4b




FIG 6




FIG 4c

FIG 7

Fig. 1 is a perspective view of a cable assembly 10. The assembly includes a cable 70 with a central core 71 and a jacket 72. A sleeve 80 is positioned on the right end of the cable, and a sleeve 80' is positioned on the left end. The sleeve 80 has a flange 81. A wavy line A indicates a break in the cable.

BEST AVAILABLE COPY